




Date: <b>2021-02-23</b>	Client: <i>ABC</i>	Job ID:	Project:	Operator: <i>John Doe</i>
Time: <b>08:58:34</b>	Cleaned: <b>Cleaned prior to the inspection</b>	Pipe Asset ID:	Barrels Amount:	Manhole Start: <b>mh1</b>

Suburb: <b>palm beach</b>	Weather: <b>No precipitation</b>	US MH: <b>mh1</b>
Road: <b>1525 gold coast highway</b>	Flow control: <b>Downstream</b>	US Depth: <b>mh1/b</b>
Location: <b>On property with buildings</b>	Direction: <b>Downstream</b>	DS MH: <b>mh1/b</b>
	Length:	DS Depth:
Purpose: <b>Final control of new construction</b>	Pipe Shape: <b>Circular</b>	
Usage: <b>Carry only surface water</b>	Width / Height: <b>300mm</b>	
Type: <b>Gravity</b>	Pipe Material: <b>Polyethylene</b>	
	Year laid:	
Comments:		

0.00m (mh1)



49.43m (mh1/b)




**SOUTHERN  
CROSS**  
*Environmental Services*


# Inspection Report

18 Neon Street  
Sumner Park, QLD 4074  
ph; 07 3376 0856


Date: <b>2021-02-23</b>	Client: <b>alto civil</b>	Job ID:	Project:	Operator: <b>chris withers</b>
Time: <b>08:58:34</b>	Cleaned: <b>Cleaned prior to the inspection</b>	Pipe Asset ID:	Barrels Amount:	Manhole Start: <b>mh1</b>



(1)




(2)



(3)



(4)



(5)



(6)



Date: <b>2021-02-23</b>	Client: <b>alto civil</b>	Job ID:	Project:	Operator: <b>chris withers</b>
Time: <b>08:58:34</b>	Cleaned: <b>Cleaned prior to the inspection</b>	Pipe Asset ID:	Barrels Amount:	Manhole Start: <b>mh1</b>

